

General Environmental Incident Summary

Incident: 4172 **Date/Time Notice:** 7/18/2016 **DEM Incident No:**

Responsible Party: Jomax Construction

Date Incident: 7/9/2016 **Time Incident:** 1030 **Duration:**

County: McKenzie **Twp:** 151 **Rng:** 98 **Sec:** 35 **Qtr:** NW

Lat: 47.86842 **Long:** -103.19370 **Method:** Navigation quality GPS

Location Description: 30th ST NW & 121st Ave NW

Submitted By: Nadia Kyrylova

Affiliation: ONEOK

Address: 896 25th St SE

City: Sidney

State: MT

Zip: 59270

Received By:

Contact Person: Mike Fritzel
5047 Jackson St.
Williston, ND 58801

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Spill- Equipment Failure

Description of Released Contaminant: Antifreeze

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Antifreeze release due to equipment Failure.

Risk Evaluation:

Minimal

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

Minimal

Action Taken or Planned:

Spill kit deployed, substance soaked up with absorbent pads; Impacted soil removed for proper disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/22/2016 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Spoke with the company contact via telephone on 7/22/16. Company representative discussed the release was approximately one-half gallon of anti-freeze which was noticed, removed and fixed. Area impacted was approximately 3 feet in diameter and 8 inches deep. Photos were taken and will be forwarded to the NDDoH. Follow-up needed.

Date: 7/22/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

Release, due to an equipment failure, impacted soils in the working area. More follow-up needed.